



Gullies not flush with the pavement



Gullies not flush with the pavement



Manholes in cycle lane



Grass encroaching cycle facilities



Grass encroaching cycle facilities



Gullies not flush with the pavement

Manholes in cycle lane



Manholes in cycle lane



Poor pavement condition



Grass encroaching cycle facilities



Poor pavement condition




Manholes in cycle lane/track



Traffic blocking cycle lane



Shrub is encroaching on footpath resulting in pedestrians walking into cycle lane which may result in a cyclists/pedestrian collision. Cut back vegetation.



Legend

- Two-way cycle facilities
- Cycle facilities on both sides
- Cycle facilities on one side
- No Cycle facilities
- Cycle facilities through public area
- - Proposed scheme
- Shared use area with bicycle bays
- Luas Stop with bicycle racks
- Sports ground
- T Toucon crossing provided
- NT No toucon crossing provided
- P Roadside cycle stands



Client:



Rev.	Comment	Date
3.0	Final	07/03/19
2.0	Draft	06/09/18
1.0	Draft	03/09/18

Notes:

- 1 Do Not Scale - use figured dimensions only.
2. Drawing is the property of PMCE Ltd.
3. OS Map is property of Sandyford Business District

Project:

**Sandyford Business District
Cycle Infrastructure Review**

Drawing Title:

**Enforcement and
Maintenance Issues**

Drawn:

MAH

Checked:

DOB

Approved:

DOB

Drawing No:

P18-055-DG-005

Date:

07/03/2019

Scale:

NTS A3

Status:

Draft

Revision:

D3